



QUICK START GUIDE



optimis FUSION



SLT MODE



Total energy

Total pulses

Standby/Ready

Counter reset

YAG MODE



Total energy

Total pulses

Focus Offset

-150µm,
+30µm,
+150µm,

Pulse number

1,
2 or 3
pulses

Standby/Ready

Counter reset



Refer to the user manual of **Optimis Fusion** for detailed information about the use and the safety measures.



XL_FUSION_MS_AN_20200818